

3rd on final B14

23

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) provide a piece of work benchmark.					
(1) Benchmark pillars					
vide fig-11 = 2 nos					
e to 4357.16 — R 8714 = 0.					
(1) Reference pillars 4 nos					
vide fig-7 = 6 nos					
e to 8017.88 — R 48107 =					
(2) clearing and grubbing Road land do do at ps —					
vide fig-11 = 1.08 ha					
e to 72697.86 — R 79877 = 0					
(3) Box culvert do do all					
					7924 = 0

[illegible]

SS, Invoice m

VIV00019R - 16/10/24 - 2.40MT

VIV00013Q - 16/10/24 - 2.00MT

= 4.40MT

Deduction lost work (-) = 3.927MT

= 0.471MT

~~Forly~~
~~10/11/24~~
~~T.E~~

~~T.W~~
~~05/11/24~~

~~C.F.P.~~

~~See SS~~
~~10-11-24~~