

(These four lines should be repeated at the commencement of the measurements relating to each work).

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- maintenance of Road					
From To 3 To Ruin mmsy					
To 4000v Tola under					
mmsy (Sc)					
Agency:- Vinod Devi					
Agg.no :- 82/CBD/mmsy/2020-21					
Date of start :- 28/08/2020					
Date of comp/n :- 15/11/2021					
Date of Entry :-					
(1) Restoration of Raincuts					
Repaired with soil :-					

4x	4.80	x	1.25	x	0.30	=	7.20m ³
6x	7.20	x	1.20	x	0.30	=	15.55m ³
3x	9.50	x	1.20	x	0.30	=	10.26m ³
6x	5.20	x	1.25	x	0.30	=	11.70m ³
5x	6.80	x	1.20	x	0.30	=	12.24m ³
4x	8.20	x	1.20	x	0.30	=	11.81m ³
3x	2.80	x	1.25	x	0.30	=	2.10m ³
							Qty = 70.86m ³

(2) making up of Berms

shoulders, slopping :-							
5x	7.20	x	1.20	=	43.20m ²		
6x	5.50	x	1.25	=	41.25m ²		
3x	7.50	x	1.20	=	27.00m ²		

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Qty. 2.00 Nos					
vide pg. No-38					
@ 109.74/Nos					B. 219 = 00
⑦ cutting of shrubs from					
Roadways					
Qty = 6.00 Nos					
vide pg No-38					
@ 6.73/Nos					B. = 40 = 00
⑩ Road making in					
(BT portion)					
Qty = 119.40 m ²					
vide pg. No-38					
@ 735.44/m ²					B. = 87959 = 00
⑪ Road making in (PCC					
position)					
Qty = 80.00 m ²					
vide pg. No-38					
@ 735.44/m ²					B. = 58835 = 00
⑫ maint. of Abadly					
plantal of Trees.					
Qty = 60.00 Nos					
vide pg. No-38					
@ 574.00/Nos					B. = 34440 = 00
Total B.					259734 = 00

Continuation

$$C.D.R. = 259734 = 00$$

[illegible]

Scanned with CamScanner