

Prasan Remodelling & Const Pvt Ltd
Agno - 22 SBD/2020-21

1045 Bana Simtalha Buehnei Tola Se
Manik Chak Tola M.M.G.S.Y (S.C.)
Schedule XIV-Form No. 134

Khaqania DIVISION

Alsubi SUB-DIVISION

M.G No - 11024

MEASUREMENT BOOK

[illegible]

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1/1) Restoration of main culverts with					
Soil - - do - - do - comp.					
Q/5 and 9MB. Page (49)					
67.67 m ² @ 404.06/m ² =					27351 = m
(2/2) Making up of Berms/shoulder					
- - do - - do - comp.					
Q/5 and 9MB. Page (50)					
379.58 m ² @ 60.28/m ² =					22881 = m
(3/3) Patch repair over bituminous					
Surface - - do - - comp.					
Q/5 and 9MB. Page (50)					
31.08 m ² @ 282.09/m ² =					8767 = m
(4/4) Maintenance of C.D. work slab Culvert					
- - do - - do - comp.					
Q/5 and 9MB. Page (50)					
03.10 Nos @ 2394.96/Nos =					7185 = m
(5/5) Maintenance of road signs - do comp.					
Q/5 and 9MB. Page (50)					
0.14 km @ 1104.58/km =					155 = m
(6/6) Maintenance of km & 200 m stone -					
- - do - - do - comp.					
Q/5 and 9MB. Page (50)					
0.16 km @ 637.66/km =					102 = m
					6644 = m
Add 0.10 m ² L.S. -					664 = m

Continuation

Scanned with CamScanner