

mmgsr-sc

SHREEKANT KUMAR

Schedule XLV-Form No. 134

Executive Engineer, R.W.D.

DIVISION
Tekari

Assistant Engineer, R.W.D.

SUB-DIVISION
Tekari

Measurement Book

941

Const of Road from Parachampur Kuretha Road to
Dhoti Bigha

2nd year maintⁿ bill

33

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Panchanpur					
Kurtha road to					
Dhobi bigha					
Agency- shreekanth kumar					
Agreement no- 32 SBD/mmmsy-sc/21-22					
Date of completion- 25/10/22					
Measurement					
1. Restoration of raincuts/					
berms — do —					
				ent =	121.01m ³
2. Making up of berms/					
shoulder — do —					
				ent =	672.3 ²
				ent =	672.30m ²
3. Repair of pot holes					
filled with 75mm					
WBM — do —					
				ent =	0.28m ³
④ Patch repair over potholes					
— do —				ent =	93.38m ²
⑤ Patch repair over bituminous					
surface — do —					
				ent =	93.38m ²
⑥ Crack sealing — filling of					
cracks and joints					
— do —				ent =	1992m

Continuation



Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑦ mainth of c/d works					
turne pipe culvert					
— do —				ent =	3 NO.
⑧ mainth of c/d works					
slab culvert					
— do —				ent =	4 NO.
⑨ mainth of road sign					
— do —					
				ent =	1.99 km
⑩ mainth of 200m & km					
stones — do —				ent =	1.99 km
⑪ cutting of branches					
of trees & shrubs					
— do —				ent =	12 NO.
⑫ cutting of shrubs from					
roadway — do —				ent =	1992 NO.
⑬ Trimming of grass and					
weeds — do —				ent =	4482 m ²
⑭ white washing of parapet					
walls of c/d work and					
tree trunks					
— do —				ent =	147 m ²
using					
04/09/24					
JE					

Continuation

Abstract of cost

35

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of rain cuts — do —					
ent =	121.01	m ³	P-	(33)	
itm - (1) @	Rs 404.06	=	Rs 48895.		
2. Making up berms/shoulder					
— do —					
ent =	672.30	m ²	P-	(33)	
itm - (2) @	Rs 60.28	=	Rs 40526.		
3. Repair of pot holes					
filled with 75mm WBM — do —					
ent =	0.28	m ³	P-	(33)	
itm - (3) @	Rs 8846.37	=	Rs 2477-		
4. Patch repair over pot holes — do —					
ent =	93.38	m ²	P-	(33)	
itm - (4) @	Rs 233.01	=	Rs 21758-		
5. Patch repair over bituminous surface					
— do —					
ent =	93.38	m ²	P-	(33)	
itm - (5) @	Rs 249.11	=	Rs 23262		
6. Crack sealing-filling of cracks and joints					
— do —					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ent = 1992m P- (33)					
itm - (6) @ Rs 371 = Rs 7390 =					
7) maint ⁿ of c/d works					
hume pipe culvert					
do					
ent = 3 No. P- (34)					
itm - (7) @ Rs 1166.58 =					
				Rs 3500 =	
8) maint ⁿ of c/d works					
slab culvert					
do					
ent = 4 No. P- (34)					
itm - (8) @ Rs 2394.96 =					
				Rs 9580 =	
9) maint ⁿ of road sign					
do					
ent = 1.99 Km P- (34)					
itm - (9) @ Rs 1104.59 =					
				Rs 2198 =	
10) maint ⁿ of 200m &					
Km stones					
do					
ent = 1.99 Km P- (34)					
itm - (10) @ Rs 643.17 = Rs 1280					
11) cutting of branches of					
trees & shrubs					
do					
ent = 12 No. P- (34)					
itm - (11) @ Rs 113.64 = Rs 1364					

Continuation

~~Gaining
04/09/24 less 730% below
JTE~~

material statement

- | | | | |
|---|-----------------------------------|--|--|
| ① | $E/W = 191.60 \text{ m}^3$ | | |
| ② | stone metal = 0.338 | | |
| ③ | crushed stone = 5.11 m^3 | | |
| ④ | Bitumen material = 0.3548 MT | | |

~~Gsingh~~
~~04/06/24~~
~~JE~~

