

Const. of TO3Mangari Via Pindara

11/11/54

Name of Agency - Chinta Devi

Shergathi

DIVISION

Shergathi

SUB-DIVISION

1288

MEASUREMENT BOOK

127

Sch. XLV-Form No. 134

Scanned with CamScanner

13
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	item (3)			0.31 m	
	Q	10670.69/m			3122=
(4/15.301)	patch repair over bituminous surface				
	V.T.M.B.P.H. (11)				
	item (4)			113.15 m ²	
	Q	274.93/m ²			31108=
(5/15.9)	Main Lencance of Road side				
	V.T.M.B.P.H. (11)				
	item (5)			0.20 m	
	Q	1074.51/m			229=
(6/15.11)	Main Lencance of 2m and 1m side				
	V.T.M.B.P.H. (11)				
	item (6)			0.31 m	
	Q	657.71/m			204=
(7/15.121)	cutting of branches of tree and shrubs				
	V.T.M.B.P.H. (11)				
	item (7)			10 m	
	Q	106.52/m			1065=
(8/15.1211)	cutting of shrubs from road way				
	V.T.M.B.P.H. (11)				

Continuation

Continuation