

mmmsy

Local print check (Dugthaway to
Laymed to Hony)

Somtoth Pythaway Hinyay, Motti bigaya, Nawada.

Schedule XLV-Form No. 134

E. E. P. W. D (W) Div, Rajawadi **DIVISION**

A. E. P. W. D, Mekhaya **SUB-DIVISION**

Measurement Book

m. B. No - 320. (Uen)

All year Maint

31

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/10 - Maint. of road from Lodipure chak (Rughoswa) To bound to Hukri Agency - Santosh Kumar Ag-No - 11-22/10/17/2017-20					
① Restoration of earthen cut					
3x 9.0 x 0.80 x 0.30 = 6.48 m ³					
5x 7.0 x 0.60 x 0.30 = 6.30 "					
8x 5.0 x 0.50 x 0.30 = 6.00 "					
					18.78 m ³
② Maint. of earthen shoulder					
3x 30.0 x 1.0 = 99.00 m ²					
1x 10.0 x 1.0 = 10.00 "					
					109.00 m ²
③ Maint. of B.T. road Removal filled material					
3x 2.5 x 0.50 = 3.75 m ²					
4x 3.0 x 0.80 = 9.60 "					
					13.35 m ²
④ Maint. of pot hole fill with warr					
3x 10.0 x 0.30 = 6.00 m ²					
Continuation					
4x 2.0 x 1.0 = 8.00 m ²					
					14.00 m ²

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	Abstract of work				
①	Restoration of run cul				
18.78 m ²	TMR P-31				
@ R 350-52/m ²	R 7146/-				
②	Maint. of earthen shoulder				
109.00 m ²	TMR P-31				
@ R 57-53/m ²	R 6271/-				
③	Maint. of B.T. road				
	Removed filled material				
13.33 m ²	TMR P-31				
@ R 195-99/m ²	R 2616-00				
④	Repair of pot hole with W3M.				
14.00 m ²	TMR P-31				
@ R 195-99/m ²	R 2744-00				
⑤	Patch repair with 20mm PMCA				
14.00 m ²	TMR P-32				
@ R 233-21/m ²	R 3266-00				
⑥	Maint. of H.P. culvert				
01 No.	TMR P-32				
@ R 1117-00/No.	R 1117-00				

Continuation of R 23160-00

