

## Inspection Report for Flood Damage Work

I Name of PIUs :-

II Name of Block/Road :-

Bhogtampur / Sarai Belkandi Road Ramchandra Hou  
Se Barai, Jala

(ID) For Road:

1. Damage Location/Chainage :- C.H. /
2. Damage Length :- 80m
3. Nature of Damage :- Flood
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Brick Bats, E.C Bags, Local Sand
  - (ii) Equipment's/Tools being used in Restoration works:- Tractor
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

III For Bridge:

- (i) Damage Location/Chainage :-
- (ii) Damage Length :-
- (iii) Nature of Damage :-
- (iv) Details of Restoration Works :-
- (v) Material being used in Restoration works:-
- (vi) Equipment's/Tools being used in Restoration works:-
- (vii) Procedure taken up in Restoration works:-
- (viii) Restored Length :-

Signature of J.E/A.E/L.E

*Prakash*  
14/11/24

Signature *[Signature]*  
14/11/24

Executive Engineer  
R.W.D. Works Division  
Muzaffarpur West