

गुजरात शासन द्वारा जारी किया गया दस्तावेज

सूचना संख्या: १४१०५/१८१८/१८१८/१८१८

Schedule XLV: Form No. 134

EXECUTIVE ENGINEER
DANAPUR

MMUSY SC

DIVISION

BIHITA SUB-DIVISION

DATE OF AGREEMENT → 18.9.18

MEASUREMENT BOOK

अनुमति प्राप्त

M.B. NO → 1281

Name of Work - Construction of road from
 Situation of work - Vishnupur Tola to Dhorasachak
 Agency by which work is executed - M.M.C.S.V.
 Date of measurement - Shree Santosh Kumar
 No. and date of agreement - 18.9.18
 (These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
work done					
① Bridging & filling workup bank near Pithora					
work up bank near - 1 m					
reference Pithora - 5 m					
1.2 km					
② Clearing and grubbing of road land by including any existing wild vegetation					
Joan bushes shrubs striking and trees					
$2 \times 1200 \times 3.50 = 8400 \text{ m}^2$					
$= 0.84 \text{ Hect}$					
③ Record Measurement of Subgrade and					
earth shoulder					
$33 \times 30 \times 5.42 \times 0.30 = 1609.74$					
$1 \times 10 \times 5.22 \times 0.30 = 15.81$					
1625.55					
$\frac{1625.55}{2}$					

Continuation

3rd. class Maintenance

66

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Name of Work - Vishnupur
tola to Dhannichalkola.

Agency - Santosh Kumar

Agg. No - 08/8200/2018-19

Actual Completion date

29/02/2020

<1> Restoration of drain

Cost - do. 44.

2x 8x 30x 0.40x 0.20m = 38.40m²

2x 5x 28x 0.50x 0.20m = 28.00m²

1x 4x 30x 0.40x 0.20m = 12.00m²

1x 4x 15x 0.50x 0.20m = 6.00m²

5x 1x 1x 1.50x 2.00 = 15.00m²

1x 7.10x 1.50x 1.00 = 10.65m²

<2> Making up of 13cm

Shoulder do. 15.

2x 5x 30x 0.40m = 120.00m²

2x 7x 30x 0.40m = 168.00m²

12x 5x 29x 0.40m = 116.00m²

12x 5x 29x 0.40m = 404.00m²

Abstract of work

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<1> Restoration of rain					
Out. 8 - do - do - T.H.					
Qty. Vide T.M.B P-66					
= 84.40 m ³					
@ Rs 345 = 101 m ³					
					Rs 29,126=00
<2> Making up of Berm					
Shoulder stripping of					
Excess Soil - T.H.					
Qty. Vide T.M.B P-66					
= 404.00 m ³					
@ Rs 50 = 94 m ³					
					Rs 20,580=00
<3> Repair of Pot holes					
filled with 75mm OM					
Qty. Vide T.M.B P-67					
= 5.26 m ³					
@ Rs 9167 = 63 m ³					
					Rs 48,219=00
<4> Patch Repair Over					
Pot holes - do - T.H.					
Qty. Vide T.M.B P-67					
= 70.39 m ²					
Limit 70.31 m ²					
@ Rs 256 = 161 m ²					
					Rs 18,011=00

BIP R-1.15, 936-00

70

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<5> Patch Repair Over Pavement Surface					
do - TLS					
Qty. Vide TMBP-67					
= 70.39 m ²					
Limit = 70.31 m ²					
@ Rs 267 = 93 m ²					
					Rs 18,838.00
<6> Maintenance of H.P.					
Convert - do - TLS					
Qty. Vide TMBP-68					
= 0.2 Nos.					
@ Rs 1104.3510					
					Rs 2209.00
<7> Maintenance of Road					
Sign - do - TLS					
Qty. Vide TMBP-68					
= 0.18 km					
@ Rs 1067 = 44 km					
					Rs 192.00
<8> Maintenance of 200m					
8 km/stone - TLS					
Qty. Vide TMBP-68					
= 0.18 km					
@ Rs 613 = 97 km					
					Rs 111.00

71

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
8) Cutting of branches of trees - do - 115 Qty. vide TMD P-68 = 02 Nos. @ Rs 104 = 481/- each Rs 209 = 00					
9) Felling of grass - do - 115 Qty. vide TMD P-68 = 12.00 m @ Rs 4 m - 6.75 m @ Rs 2 = 141 m Rs 14 = 00 Rs 1.37, 509 = 00 Rs 124 = 00 Rs 1.37, 385 = 00					
10) ... 11) ... 12) ... 13) ... 14) ... 15) ... 16) ... 17) ... 18) ... 19) ... 20) ...					