

2nd year maintenance
63
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:	Maintenance of				
Area:	From Shirojpur Bazaar				
P.M.L.Sy to Malahatola					
Agency: MJC Rangan Construction					
Actual date of survey: 26.12.2021					
Survey period: 27.12.22 to 26.12.23					
Date of entry: 29.12.23					
(1) Restoration of room walls					
10m -					
$4 \times 3.30 \times 0.85 \times 0.65 = 7.29$					
$14 \times 2.25 \times 0.65 \times 0.30 = 6.14$					
$9 \times 4.25 \times 1.25 \times 0.65 = 31.17$					
$9 \times 3.25 \times 1.20 \times 0.60 = 21.06 m^2$					
$3 \times 4.0 \times 0.90 \times 0.65 = 7.02$					
					$80.32 m^3$
(2) Making up beams					
Shoulder slo -					
$2 \times 160m \times 1.45 = 464. m^2$					
$2 \times 80 \times 1.55 = 248.0$					
					$712.6 m^2$
(3) Premix carpet withdraw					
Seal coat type B grade					
$2 \times 4.35 \times 2.15 = 18.7 m^2$					
$4 \times 20.5 \times 0.250 = 20.5 m^2$					
$16 \times 1.25 \times 0.30 = 6.0 m^2$					
$2 \times 5.70 \times 2.50 = 26.6 m^2$					
					$71.2 m^2$

Continuation

Sch. XLV-Form No. 134

65

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ Maintenance of road					
Sign boards visible					
item no 4 P.M. 64					
— 0.95 Km					
@ R. 1054.28 / Km					Rs. 999.0
⑤ Maintenance of 200m					
Post boards visible					
item no 5 P.M. 64					
— 1.90 Km					
@ R. 688.17 / Km					Rs. 1304
⑥ Maintenance of tree					
by road sides visible					
Visible 20m 20 ft.					
R.M. 64 — 100 m ²					
@ R. 655.50 each					Rs. 78624
					Rs. 171736..
Add G.T. 10%					Rs. 20608
Add of labours 1%					Rs. 1717.
					Rs. 194061..
Less 0.21% below					() R. 408.00
					Rs. 193653
<u>A/c</u>					
29.12.23					
5021-187.12 m ³					58 Km
Stone chippings - 1.92 m ³					
Bitumen 152.0 Kg					
RS-1 - 21.03 m ³					
Waste sand 0.42 m ³					

Continuation

A/c
29.12.23