

4th year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work: Mainl. of Road from 1021					
Bagicha Se TO Hutora					
(Crackh).					
Agency: San Ramesh Sahni.					
Agenda: 95(SBS)/2018-19					
D.O. w: 28.11.2018					
D.O. c: 27.08.2019					
Actual D.O. c: 09.08.2019					

① Restoration of Rain Cut —

$$12 \times 3.10 \times 0.40 \times 0.35 = 7.81$$

$$16 \times 3.25 \times 0.80 \times 0.30 = 12.48$$

$$15 \times 3.55 \times 0.75 \times 0.35 = 13.98$$

$$10 \times 4.00 \times 0.70 \times 0.30 = 8.40$$

$$9 \times 3.20 \times 0.85 \times 0.35 = 8.57$$

$$57.18 \text{ m}^3$$

② Maintenance of earthen

shoules —

$$15 \times 9.00 \times 0.40 = 94.50$$

$$12 \times 7.50 \times 0.85 = 76.50$$

$$14 \times 5.00 \times 0.90 = 63.00$$

$$16 \times 6.15 \times 0.80 = 78.72$$

$$326.22 \text{ m}^2$$

③ Maintenance of Hume pipe

Actual —

$$1 \times 1 = 1.00 \text{ m}^2$$

