

Kishor Kumar Singh
Agno- 13 S.B.D/2019-20

Gharana Gharat M.M.Z.VY To Macheta Patha
M.M.G.S.Y (S.C)

Measurement Book

Schedule XLV-Form No. 134

Khagaria

DIVISION

Alauli

SUB-DIVISION

M.B-1048

20th year Maintenance Bill.

48

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Cost of Road from Lphansat					
from 2V to Dik Mactra.					
Name of Agency:- Kishor Kumar Singh.					
No. of Agreement:- 13.500/019-20.					
Date of work order:- 02/03/020.					
Actual Date of Completion:- 20/06/021.					
(Complete works)					

① Restoration of main Cuts with					
80% - do - do - Comp. E/P.					
1x9x	1.10x	0.80x	0.40 =	3.17 m	
1x9x	4.75x	$\frac{0.9+0.8}{2}$	x 0.60 =	21.81 m	

1x6x	5.10x	$\frac{0.6+0.5}{2}$	x 0.40 =	6.73 m	
1x13x	7.40x	$\frac{0.9+0.4}{2}$	x 0.50 =	32.26 m	
1x14x	4.05x	$\frac{1.10+0.80}{2}$	x 0.40 =	21.55 m	
				84.53 m	

② making up of Berms/shoulder stripping					
excess 80% - do - do - comp. E/P.					
1x7x	1.05x	0.90	— =	6.62 m	
1x8x	5.25x	$\frac{0.9+0.8}{2}$	— =	35.70 m	
1x9x	5.50x	$\frac{0.6+0.70}{2}$	— =	32.17 m	
1x12x	8.10x	$\frac{0.9+0.50}{2}$	— =	68.04 m	
1x15x	5.30x	$\frac{1.10+0.90}{2}$	— =	79.50 m	
1x7x	8.20x	$\frac{1.5+1.70}{2}$	— =	71.84 m	
				313.87 m	

③ Repair of Pot holes filled over

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of road cut with soil		do	do	do	
Qty used G.M.B. Page (48)					
	84.53 m ² @	377.57/m ²			32087 = m
② Restoration making up of Dams & Blower		do	do	comp.	
Qty used G.M.B. Page (48)					
	313.87 m ² @	56.81/m ²			178312 = m
③ Repair of pot hole with W.B.M.		do	do	comp.	
Qty used G.M.B. Page (49)					
	64.93 m ² @	279.43/m ²			18143 = m
④ Repair of pot hole over concrete		do	do	comp.	
Qty used G.M.B. Page (49)					
	64.93 m ² @	219.50/m ²			14252 = m
⑤ Patch repair over bituminous surface		do	do	comp.	
Qty used G.M.B. Page (49)					
	64.93 m ² @	237.13/m ²			15397 = m
⑥ Maintenance of CD work H.P.		do	do	comp.	
Qty used G.M.B. Page (50)					
	01.00 Nos @	1102.80/No			1103 = m
⑦ Maintenance of CD work slab culvert		do	do	comp.	

Continuation

52
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Qty used 9MB. Page (50)					
0.10 Nos @ 227347 / Nos =					227347
(8) Maintenance of road byns - do - do					
Qty used 9MB. Page (50)					
0.18 Nos @ 1054.58 / Nos =					190.7
(9) Maintenance of L.M. & 200m Stone					
- do - do - do - do - do					
Qty used 9MB. Page (50)					
0.22 Nos @ 617.34 / Nos =					135.7
(10) Cutting of Shorbs on road side -					
- do - do - do - do - do					
Qty used 9MB. Page (50)					
2.00 Nos @ 106.12 / Nos =					212.2
					21623.10
(11) Providing & laying of hot asphalt					
Thermoblastic Compound - do - do					
Qty used 9MB. Page (50)					
240.00 m @ 735.40 / m =					176496.00
					278119.00
Add - 0.00%					2781.00
" 12.00%					33374.00
					314274.00
Less @ 0.07% per agreement					220.00
					314054.00

Continuation


 22/10/24
 J.F.
 22/10/24
 B.E.