

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E. RWD, Works Division Aranta	
Name of Block/Road :- Palasi/ Bari chowk to Dharamganj Bt. 2	
A. For Road	
1. Damage Location/Chainage :- 0.900, 0.920 and 0.940 km	
2. Damage Length :- 16-90	
3. Nature of Damage (Length Wise)	(i) Breach :- ✓
	(ii) Crust Damage :-
	(iii) Only Flank Damage :-
whether traffic fully/Partially obstructed :- Fully obstruct	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- Local sand, EC bag, Bamboo, brick bats	
(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Tractor	
(iii) Restored Length	In open Area :- ✓
	In habitation Area :-
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	} N/A
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory	

12/11/24

12/11/24

12/11/24
Signature of Inspector
(Official Seal)