

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- P.W.D work Division ~~Lakhigada~~ Khurapur, Purapur

Name of Block/Road :- Motorable Road from Babhangana Nimchak

A. For Road TO Narendarganj Road

1. Damage Location / Chainage:- 1.8 KM

2. Damage Length 46 m

3. Nature of Damage (Length wise)

(i) Breach :- 30 m

(ii) Crust Damage :- 16 m

(iii) Only Flank Damage

Whether Traffic Fully/Partialily Obstructed :-

4. Details of Restoration

(i) Material Being Used in Restoration :- Brick bats, G.S.B.

(ii) Equipment/ Tools being Used in Restoration Works :- Tractor, J.E.B, Roller

(iii) Restored Length

In Open Area :- 46 m

In Habitation Area :-

(iv) If Restoration work done in habitation Area Give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1. Damage Location / Chainage:-

2. No. of Span Damage

3. Length of Span

4. Nature of Damage (Pier/ Abutment/Wing wall/Approach Road Damage)

5. Details of Restoration

(i) Material Being Used in Restoration :-

(ii) Equipment/ Tools being Used in Restoration Works :-


(iii) Restored Length

In Open Area :-

In Habitation Area :-

Overall Grade of Restoration Work (Satisfactory/Unsatisfactory)


18/11/24
76


12/11/24
Signature of Inspector
(Official Seal)