

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- R.W.D work Division ~~Kharagpur~~ Kharagpur - Tarpur

Name of Block/Road :- Motorable Road from NH-80 Suryagarha to

A. For Road Koyalwa Barabewa Binda Toli

1. Damage Location / Chainage:- 2.5km to 3.5 km

2. Damage Length 381 m

3. Nature of Damage (Length wise)

(i) Breach :- 155 m

(ii) Crust Damage :- 226 m

(iii) Only Flank Damage

Whether Traffic Fully/Partialily Obstructed :-

4. Details of Restoration

(i) Material Being Used in Restoration :- Brick bats, GSB grit

(ii) Equipment/ Tools being Used in Restoration Works :- Tractor, J.C.B, Roller

(iii) Restored Length

In Open Area :- 381 m

In Habitation Area :-

(iv) If Restoration work done in habitation Area Give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1. Damage Location / Chainage:-

2. No. of Span Damage

3. Length of Span

4. Nature of Damage (Pier/ Abutment/Wing wall/Approach Road Damage)

5. Details of Restoration

(i) Material Being Used in Restoration :-

(ii) Equipment/ Tools being Used in Restoration Works :-

(iii) Restored Length

In Open Area :-

In Habitation Area :-

Overall Grade of Restoration Work (Satisfactory/Unsatisfactory)

18/11/24
oe

Signature of Inspector
(Officail Seal)