

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD works Division Anand

Name of Block/Road :- Palasi / 2027, Karon to Chhapani

A. For Road

1. Damage Location/Chainage :- 0.200 km

2. Damage Length :- 90 m

3. Nature of Damage (Length Wise) (i) Breach :- ☒
(ii) Crust Damage :- ☐
(iii) Only Flank Damage :- ☐

whether traffic fully/Partially obstructed :-

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Local Sand, Bamboo, Ec bags, etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor, JCB

(iii) Restored Length
In open Area :-
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-
(2) No. of Span Damage :- N/A
(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-
(ii) Equipment/Tools Being Used in Restoration Works :-
(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

[Signature]
6/11/24

[Signature]
6/11/24

[Signature]
6/11/24

[Signature]
Signature of Inspector
(Official Seal)