INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- EE RWA WORKS Division Anania
Name of PIUs:- EE RWD Works Division Anania Name of Block/Road:- Paladi / 2054-2029 to Pachaili
A. For Road
1. Damage Location/Chainage:- (-700 kg
2. Damage Length: 77.2 m
3. Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage :-
(iii) Only Flank Damage :-
whether traffic fully/Partially obstructed:-
4. Details of Restoration:
(ii) Material Being Used in Restoration: - Brick bet Local Sand (iii) Equipment/Tools Being Used in Restoration Works: - Tractor JCB
(ii) Equipment/Tools Being Used in Restoration Works:- てってもっていていている。
(iii) Restored Length In open Area:-
In habitation Area:-
(iv) If Restoration work done in habitation Area give Reason:-
B. For Bridge (Size of Bridge/Culvert)
(1) Damage Location/Chainage:-
(2) No. of Span Damage:-
(3) Length of Span:-
(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage):-
5) Details of Restoration:-
i) Material Being Used in Restoration:-
ii) Equipment/Tools Being Used in Restoration Works:-
iii) Restored Length :-
1 (G i C i motisfactory):- C a h l h la
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory
Que s July and Inspector
Signature of Inspector
(Official Seal)
11/hy