

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Works Division Anand

Name of Block/Road :- Tokhat / Tekni Bhonra PMGSY bhonra to Parhoili

Harunan
Mandir

A. For Road

1. Damage Location/Chainage :- 1.0 km

2. Damage Length :- 37.5m 18m (55.5m)

3. Nature of Damage (Length Wise) (i) Breach :- Breach Damage
(ii) Crust Damage :- Crust Damage
(iii) Only Flank Damage :- —

whether traffic fully/Partially obstructed :- fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick Bat, Local Sand, Ec bag, Bamboo etc

with tally

(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Roller, Tractor

(iii) Restored Length In open Area :- 37m open Area
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Prasad
4/11/24
are

6/11/24

Signature of Inspector
(Official Seal)