

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Works Division Anantnag	
Name of Block/Road :- Palasi / Sohadi via sanda to Lakankotta Jk	
A. For Road	
1. Damage Location/Chainage :- 0.8 km, 0.9 km, 1.05 km, 1.2 km, 1.5 km	
2. Damage Length :- 68 m	
3. Nature of Damage (Length Wise)	(i) Breach :- <input checked="" type="checkbox"/>
	(ii) Crust Damage :- <input type="checkbox"/>
	(iii) Only Flank Damage :- <input type="checkbox"/>
whether traffic fully/Partially obstructed :- fully	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- Brick bats, local sand, Bamboo etc	
(ii) Equipment/Tools Being Used in Restoration Works :- Tractor, JCB	
(iii) Restored Length	In open Area :- <input checked="" type="checkbox"/>
	In habitation Area :- <input type="checkbox"/>
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	2 N/A
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory	

14/11/24
18/11/24
DE

14/11/24
18/11/24

14/11/24
18/11/24

14/11/24
Signature of Inspector
(Official Seal)