

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- RWD works Division Anaria

Name of Block/Road :- Palosi / PMGSY Budhi to Gosayipur

A. For Road

1. Damage Location/Chainage :- 0.500 km, 1.00 km

2. Damage Length :- 93m

3. Nature of Damage (Length Wise) (i) Breach :- ☒
(ii) Crust Damage :- ☐
(iii) Only Flank Damage :- ☐

whether traffic fully/Partially obstructed :- Fully obstruct

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Bamboo, brick bats, local sand, etc bags etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with trolley, JCB etc

(iii) Restored Length In open Area :- ☒
In habitation Area :- ☐

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

}

N/A

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

12/11/24
Signature of Inspector
(Official Seal)

12/11/24

12/11/24

12/11/24