INSPECTION REPORT FOR MOTORABLE WORK

A IOI ECTION REI	
Name of PIUs:- EE RWD 1	vorus Division Anaria
Name of Block/Road :- Jakika	at 1 Tekni Bhaibna PMGsy Takni to Tonkni Vic
A. For Road	of 1 Tekni Bhaibna PMGsy Takni to Tonkni Vic Hanijan tola Bhonua
1. Damage Location/Chainage :- A	1 Ch. OIJFO KM
2. Damage Length: 49 m	
3. Nature of Damage (Length Wise)	(i) Breach: Breach Samage (ii) Crust Damage: Crust Damage
-	(ii) Crust Damage: - Crunt Damage
	(iii) Only Flank Damage:-
whether traffic fully/Partialiy obstruction	eted:- fully
4. Details of Restoration:	the said the base to Page brickets of
(1) Material Being Used in Restoration	on: Tocal Sand, Damboo, et bugg, of
(ii) Equipment/Tools Being Used in	on: Local Sand, Bamboo, Ec Dags, brickets of Restoration Works: JeD, Roller, Tractor with troller
(iii) Restored Length	In open Area:- Open Area
	In habitation Area:-
(iv) If Restoration work done in habit	ation Area give Reason :-
B. For Bridge (Size of Bridge/Cu	llvert)
(1) Damage Location/Chainage :-	
2) No. of Span Damage :-	
3) Length of Span :-	
4) Nature of Damage (Pier/Abuttmer	nt/
Wing Wall/Approach Road Damage)	:-
5) Details of Restoration:-	
i) Material Being Used in Restoration	1:-
ii) Equipment/Tools Being Used in R	estoration Works :-
iii) Restored Length :-	
	0
Overall Grade of Restoration work	(Satisfactory/Unsatisfactory):- Sahsfactory
0	Mas Gillay
2000	Signature of Inspector (Official Seal)
W W W W W W W W W W W W W W W W W W W	(Official Seal)
and the same of th	,