

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- RWD (W) Div. ~~Kharappur~~ Kharappur - Turapur

Name of Block/Road :- Motorable Road NH 80 Mulky Dhale to Ashaypur.

A. For Road

1. Damage Location / Chainage:- 0.50km to 6km

2. Damage Length 1218m

3. Nature of Damage (Length wise)	(i) Breach :- 277m
	(ii) Crust Damage :- 941m
	(iii) Only Flank Damage

Whether Traffic Fully/Partialily Obstructed :-

4. Details of Restoration

(i) Material Being Used in Restoration :- Brick's bats , GSB 3rd

(ii) Equipment/ Tools being Used in Restoration Works :- Tractor , J.C.B. Roller.

(iii) Restored Length	In Open Area :- 1218m
	In Habitation Area :-

(iv) If Restoration work done in habitation Area Give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1. Damage Location / Chainage:-

2. No. of Span Damage

3. Length of Span

4. Nature of Damage (Pier/ Abutment/Wing wall/Approach Road Damage)

5. Details of Restoration

(i) Material Being Used in Restoration :-

(ii) Equipment/ Tools being Used in Restoration Works :-

(iii) Restored Length	In Open Area :-
	In Habitation Area :-

Overall Grade of Restoration Work (Satisfactory/Unsatisfactory)

18/11/24
26

Signature of Inspector
(Official Seal)