

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Works Division, Anarua
Name of Block/Road :- Kurnakatta/sandan Tola Chikni L041 toward No -12

A. For Road

1. Damage Location/Chainage :- 0.300 KM , 0.500 KM

2. Damage Length :- 36.00 M

3. Nature of Damage (Length Wise) (i) Breach :- Breach Damage
(ii) Crust Damage :- Crust Damage
(iii) Only Flank Damage :- —

whether traffic fully/Partially obstructed :- fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Bamboo Piling, E.C Bag, local sand Bricks
etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with Trolley, Roller, JCB
etc

(iii) Restored Length In open Area :- Open Area

In habitation Area :- —

(iv) If Restoration work done in habitation Area give Reason :- —

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

[Signature]
11/11/24

[Signature]
18/11/24
Signature of Inspector
(Official Seal)