

प्रतिवेदन

पथ का नाम - **kushmaidu to Hulewadi**

कार्य का नाम - **FDR/2021-25**

मेरे बाद से कातिगरत मांग में यातायात चालू करने का कार्य।

संलग्न प्राक्कलन 2024 को पखाड़ मेरी गीधण बाद से कातिगरत **kushmaidu to Hulewadi** मेरे बाद कातिगरत मरम्मति मद से कातिगरत चालू करने हेतु तथार किया गया है जिसकी पार्किंग लागत **3847166/-** है। उक्त पथ का नियन **Brick Bats** यानान्तर्गत हुआ है एवं योजना अनुसार **Hume Pipe, Bamboo, लोकल बालू** एवं **Brick Bats** द्वारा के बाद यातायात चालू कराया गया है। पथ के विभिन्न हिस्से में कराये गये कार्य का विवरणी स्पष्ट रूप से प्राक्कलन में दर्शाया गया है। प्राक्कलन मदों का दर वर्तमान अनुरुद्धरण दर के अनुरूप है।

12/11/24

कर्नीव अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रशास्ता, *Ramdasgong*

12/11/24

राहायक अभियंता,
ग्रामीण कार्य विभाग
कार्य अवर प्रमण्डल, *Ramdasgong*

12/11/24

कायपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, *Ramdasgong*

Inspection Report for Flood Damage Work

Date : 12/11/24

1 Name of PII's:- EE Forbesgan

2 Name of Block :- Forbesganj

3 Name of Roads:- Kushanuher to Hatewar

A For Road

1 Damage Location/Chainage :- CH- 50M, 600M, 800M, 900-1000

2 Damage Length :- 156.5M

3 Nature of Damage :- Wash out

4 Details of Restoration Works:-

(i.) Material being used in Restoration Works:-

(ii.) Equipments/Tools being used in Restoration works:-

(iii.) Procedure taken up in Restoration works:-

(iv.) Restored Length :- 156.50M

B For Bridge

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of Damage :-

4 Details of Restoration Works:-

(i.) Material being used in Restoration Works:-

(ii.) Equipments/Tools being used in Restoration works:-

(iii.) Procedure taken up in Restoration works:-

(iv.) Restored Length :

✓ 12/11/24
J.B

Signature of JE/AE/EE

✓ 12/11/24

✓ 12/11/24
BILLY

✓ 12/11/24
RUBI

Signature

(Name of Inspector)