

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E. RWD, Nepal Division - Aranya

Name of Block/Road :- Aranya / Chorgharia to Ranghaha via Madhopora.

A. For Road

1. Damage Location/Chainage :- 5.50 km

2. Damage Length :- 15 mtr.

3. Nature of Damage (Length Wise)

(i) Breach :-	Breach Cutting
(ii) Crust Damage :-	Crust damage
(iii) Only Flank Damage :-	

whether traffic fully/Partially obstructed :- fully.

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Bamboo, local Sand, etc Bag, Brick Bath etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with folly, etc, Roller, etc.

(iii) Restored Length

In open Area :-	15 mtr.
In habitation Area :-	

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector
(Official Seal)

11/11/24
AT