INSPECTION REPORT FOR MOTORABLE WORK

Name of 103. EE RWA MOSTRA Alvinia - Amaria	
Name of PIUs: - EE RWD WOOKD Division Anonia Name of Block/Road: - Polani / Deepnagar to Dolwani A. For Road	_
A. For Road	_
Demage Location/Chainage	
0., 00 4 2	
2. Damage Length:- 32 m	
3. Nature of Damage (Length Wise) (i) Breach :-	
(ii) Crust Damage :-	
(iii) Only Flank Damage :-	
whether traffic fully/Partially obstructed:-	
4. Details of Restoration:-	
(i) Material Being Used in Restoration: - 1) nick both, Ec bog, Local Sa	7
(i) Material Being Used in Restoration: - Prick both, Ec bog, Local Sa (ii) Equipment/Tools Being Used in Restoration Works: - Tracky, JCB	
(iii) Restored Length In open Area :-	
In habitation Area:-	
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
1) Damage Location/Chainage :- (
	-
2) No. of Span Damage:-	
3) Length of Span:-	
) Nature of Damage (Pier/Abuttment/	
Ying Wall/Approach Road Damage) :-	
Details of Restoration :-	\neg
	-
Material Being Used in Restoration:-	_
Equipment/Tools Being Used in Restoration Works:-	_
Restored Length :-	
verall Grade of Restoration work (Satisfactory/Unsatisfactory):-Squafed	
ciali Grade of Restoration work (Batisfactory, Singulation St. 1977)	
11/24	
V M. (1211)	
Gi-Dayna of Inguestor	
Signature of Inspector	
Signature of Inspector (Official Seal)	