

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- R.W.D work Division ~~Lakhisar~~ ^{Kharagpur, Garabur}

Name of Block/Road :- Motorable Road from Ramchandarpur Pamenayal

A. For Road at Sri Krishna Chok to Harinar Gola via High School yakhtay Ashan.

1. Damage Location / Chainage:- 0.3 KM to 0.6 KM

2. Damage Length 136 m

3. Nature of Damage (Length wise)

(i) Breach :- 55 m

(ii) Crust Damage :- 81 m

(iii) Only Flank Damage

Whether Traffic Fully/Partialily Obstructed :-

4. Details of Restoration

(i) Material Being Used in Restoration :- Brick bat, GSB grb

(ii) Equipment/ Tools being Used in Restoration Works :- Tractor, J.C.B. Roller

(iii) Restored Length

In Open Area :- 136 m

In Habitation Area :-

(iv) If Restoration work done in habitation Area Give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1. Damage Location / Chainage:-

2. No. of Span Damage

3. Length of Span

4. Nature of Damage (Pier/ Abutment/Wing wall/Approach Road Damage)

5. Details of Restoration

(i) Material Being Used in Restoration :-

(ii) Equipment/ Tools being Used in Restoration Works :-

(iii) Restored Length

In Open Area :-

In Habitation Area :-

Overall Grade of Restoration Work (Satisfactory/Unsatisfactory)

[Signature]
12/11/24
JL

[Signature]
Signature of Inspector
(Official Seal)