

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- *EE RWD Works Division Arana*

Name of Block Road :- *Arana/Girjanand Mandal To Grajai Tola*

A. For Road

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage (Length Wise)

(i) Breach :-	<i>Breach</i>
(ii) Crust Damage :-	<i>Crust Damage</i>
(iii) Only Flank Damage :-	

whether traffic fully/Partially obstructed :- *fully*

4. Details of Restoration :-

(i) Material Being Used in Restoration :- *Loam Sand, Bamboo, Ec Bag, Brick Bats*

(ii) Equipment/Tools Being Used in Restoration Works :- *Tractor with trolley, Roller & Screener*

(iii) Restored Length

In open Area :-	<i>43m</i>
In habitation Area :-	

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- *Satisfactory*

11/11/24

11/11/24
100

15/11/24
Signature of Inspector
(Official Seal)