

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWA Works Division Anarica

Name of Block/Road :- Jukinat / Matiyani Rakhipur PMGSY Dita to

A. For Road Boka Mohan River Choki West

1. Damage Location/Chainage :- 150 m, 225 m

2. Damage Length :- 63 m

3. Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage :-
(iii) Only Flank Damage :- flank Damage

whether traffic fully/Partially obstructed :- Partially

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Local sand, Bamboo Filing, Ec bags etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with trolley, JCB, Roller

(iii) Restored Length In open Area :- open Area
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

11/11/24

11/11/24

Signature of Inspector
(Official Seal)