

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Works Division Anantnaga

Name of Block/Road :- Palasi / Baluganj to Maldwar

A. For Road

1. Damage Location/Chainage :- 0.500, 0.700, 1.0 km

2. Damage Length :- 50 m

3. Nature of Damage (Length Wise) (i) Breach :- ☒
(ii) Crust Damage :- ☐
(iii) Only Flank Damage :- ☐

whether traffic fully/Partially obstructed :- Fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick bat, Local Sand, EC bags etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor, JCB

(iii) Restored Length
In open Area :- ☒
In habitation Area :- ☐

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :- } N/A
(2) No. of Span Damage :- }
(3) Length of Span :- }

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature
06/11/24
OC

Signature
06/11/24
OC

Signature
06/11/24
OC

Signature of Inspector
(Official Seal)