

प्रतिवेदन

पथ का नाम - Rampur to Rampur west

कार्य का नाम - F.D.R/2024-25

मेरे बाट सोहोगरता भाग में प्राक्कलन जल्द आवश्यक हो गया।

संस्था परिवर्तन 2024 की वर्षाकाल में इनी मैट्रिक्यूल वाहन से कृषि यातायात में बाढ़ अधिगरता सरमर्ति महत्व वाली यातायात चालू करने हेतु योग्य किसी विकास का

प्राक्कलन लागत 111136 = 00

का निवाप NABARD यातायात हुआ है एवं योग्य अनुरक्षण यातायात में है।

पथ के बाट (अतियरक्त) भाग में आवश्यकता अनुसार Hume Pipe, Bamboo, लौकल चालू हो।
Brick Bats देने के बाद यातायात चालू कराया गया है। पथ के विभिन्न हिस्से में कराये गये काम का विवरणी रूप से प्राक्कलन में दर्शाया गया है।

प्राक्कलन मदो का दर वर्तमान अनुरुचित दर के अनुरूप है।

111136
कर्तव्य अभियंता,

ग्रामीण कार्य विभाग,

कार्य प्रशासन Forbesganj

12/11/24
सहायक अभियंता

ग्रामीण कार्य विभाग

कार्य अधर प्रमण्डल Forbesganj

12/11/24
कायपालक अभियंता,
ग्रामीण कार्य विभाग

कार्य प्रमण्डल Forbesganj

Inspection Report for Flood Damage Work

Date : 12/11/24

- 1 Name of PWD :- E.E R.W.D Forbesganj
- 2 Name of Block :- Forbesganj
- 3 Name of Roads :- Ramapur to Ramapur-west

A For Road

- 1 Damage Location/Chaining :-
- 2 Damage Length :- 8.90m, 11.20m, 6.50m, 21.40m, 12.90m, 17.10m,
- 3 Nature of Damage :- Washout 4.00m
- 4 Details of Restoration Works:-
 - (i) Material being used in Restoration Works:- L-Sand, B/Bags, Bamboo, EcBags
 - (ii) Equipments/Tools being used in Restoration works:- Tractor, JCB
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored length :-

B For Bridge

1. Damage Location/Chaining :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works:-
 - (i) Material being used in Restoration Works:-
 - (ii) Equipments/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

N/A

RRD
12/11/24
Signature of JE/AE/EE

R
12/11/24
BCE

R
12/11/24
Signature

(Name of Inspector)

D
12/11/24