

# INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- RWD WORKS DIVISION, NAVGACHHIYA	
Name of Block / Road :- GOPALPUR / MIDDLE SCHOOL MIYA TOLI SE SANITY (SANJAY) SINGH HOME	
<b>A. For Road</b>	
1. Damage Location / Chainage :- 0-40m, 350-370m	
2. Damage Length :- 51m	
3. Nature of Damage (length wise)	(i) Breach :-
	(ii) Crust Damage :- 10m
	(iii) Only Flank Damage 41m
whether traffic fully/Partialily obstructed - Partially obstructed	
4. Details of Restoration :	
(i) Material Being Used in Restoration : Brick Bats	
(ii) Equipment / Tools being Used in Restoration Works : front end loader, Tractor	
(iii) Restored length	In open Area :- 51m
	In habitation Area :-
(iv) if Restoration work done in habitation Area give Reason :-	
<b>B. For Bridge (Size of Bridge / Culvert)</b> —	
1. Damage Location / Chainage : —	
2. No. of Span Damage :- —	
3 Length of Span —	
4 Nature of Damage (Pier / Abutment/Wing wall/Approach Road Damage) —	
5. Details of Restoration : —	
(i) Material Being Used in Restoration : —	
(ii) Equipment / Tools being Used in Restoration Works : —	
(iii) Restored length	In open Area :- —
	In habitation Area :- —
Overall Grade of Restoration Work (Satisfactory / Unsatisfactory) Satisfactory.	

Sales  
14/11/24  
J.E

ME  
14/11/24

Shu  
14/11/24  
ET

Priyam  
14/11/24  
Signature of Inspector  
(Official Seal)  
Executive Engineer  
RWD Works Division  
BANKA-1