

# INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- P.W.D. WORK Division, ~~Farakka~~ Kharypur Farakka

Name of Block/Road :- Motorable Road Groom Jaitpur Khutha Groom  
Road to Kabiistan Se Harigan to lhotekue Basic School.

## A. For Road

1. Damage Location / Chainage:- 0 to 1 KM

2. Damage Length 256 m

3. Nature of Damage (Length wise)

(i) Breach :- 16 m

(ii) Crust Damage :- 240 m

(iii) Only Flank Damage —

Whether Traffic Fully/Partialily Obstructed :-

## 4. Details of Restoration

(i) Material Being Used in Restoration :- Bricks, G.S.B

(ii) Equipment/ Tools being Used in Restoration Works :- Tractor, J.C.B, Roller

(iii) Restored Length

In Open Area :- 256 m

In Habitation Area :-

(iv) If Restoration work done in habitation Area Give Reason :-

## B. For Bridge (Size of Bridge/Culvert)

1. Damage Location / Chainage:-

2. No. of Span Damage

3. Length of Span

4. Nature of Damage (Pier/ Abutment/Wing wall/Approach Road Damage)

## 5. Details of Restoration

(i) Material Being Used in Restoration :-

(ii) Equipment/ Tools being Used in Restoration Works :-

(iii) Restored Length

In Open Area :-

In Habitation Area :-

Overall Grade of Restoration Work (Satisfactory/Unsatisfactory)

18/11/24  
St

Signature of Inspector  
(Official Seal)