


प्रतिवेदन

पथ का नाम :- L026 Yadav to 19 Ward No-13 Parkpur to Baluha
कार्य का नाम :- PDR-2024 to 19 Gramchi Nagar Khayur
में बाढ़ से क्षतिग्रस्त भाग में यातायात चालू करने का कार्य।


संलग्न प्राक्कलन 2024 को प्रखण्ड में आरी भीषण बाढ़ से क्षतिग्रस्त L026 Yadav to 19 Ward
No-13 Parkpur to Baluha to 19 Gramchi Nagar Khayur
में बाढ़ क्षतिग्रस्त मरम्मत में से यातायात चालू करने हेतु तैयार किया गया है जिसकी
प्राक्कलित लागत 1310836.00 है। उक्त पथ
का निर्माण m.m.s.y (S) गानान्तर्गत हुआ है एवं योजना अनुसंधान अर्द्ध में 31
पथ के कटे (क्षतिग्रस्त) भाग में आवश्यकता अनुसार Hume Pipe, Bamboo, लोकल बालू एवं
Brick Bats देने के बाद यातायात चालू कराया गया है। पथ के विभिन्न हिस्से में कराये गये कार्य
का विवरणी स्पष्ट रूप से प्राक्कलन में दर्शाया गया है।
प्राक्कलन मदों का दर वर्तमान अनुसूचित दर के अनुरूप है।



कनीय अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रशाखा, 21/11/2024।



सहायक अभियंता,
ग्रामीण कार्य विभाग,
कार्य अवर प्रमण्डल, 21/11/2024।



कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, फारविषय

Inspection Report for Flood Damage Work

Date:

1. Name of P.U's:- EE RWD WORK Division Farasgany

2. Name of Block:- Bharganag

3. Name of Road:- 626 yastur to/w Ward No-13 parkpar to Balubhar
to/w Gharelli' margin Khajuri

A. For Road

1. Damage Location/Chainage :-

2. Damage Length :- 50 M, 100 M, 130 M 100 M 1120 M, 1200 M

3. Nature of Damage :- 5.00 M 14.00 M 5.20 M, 6.00 M, 8.10 M 6.20 M

4. Details of Restoration Works:-

(i.) Material being used in Restoration Works:- L. Sand, B/Dark, Ec Bags, Bamboo

(ii.) Equipments/Tools being used in Restoration works:- TCB, Tractor

(iii.) Procedure taken up in Restoration works:-

(iv.) Restored Length :-

B. For Bridge

1. Damage Location/Chainage:-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works:-

(i.) Material being used in Restoration Works:-

(ii.) Equipments/Tools being used in Restoration works:-

(iii.) Procedure taken up in Restoration works:-

(iv.) Restored Length :-

Signature of JE/AE/EE

12/11/2024
AE

Signature

(Name of Inspector)

12/11/24

Scanned with OKEN Scanner

Scanned with OKEN Scanner

Scanned with OKEN Scanner