INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs: - 1715 Out
Mand of Plack/Pood of RW/> Works Sivioion Alyania
Name of Block Road: - Polosi 1 Bhangoro Mone to Kachmoh Tolg
Name of PIUs: - EE RWD WOYKD Divioion Avania Name of Block/Road: - Polosi 1 Bhangoro Mone to Kacchmoh Tola A. For Road
1. Damage Location/Chainage:- 0.650 Km
2. Damage Length: 24.7m
Nature of Democe (Level IV)
3. Nature of Damage (Length Wise) (i) Breach: Breach Cuffing
(II) Clust Damage:-
(iii) Only Flank Damage:-
whether traffic fully/Partially obstructed:-
4. Details of Restoration:
1) Material Bellig Used in Restoration: - focal Sand, Ec bogs, Brick Vota etc
i) Material Being Used in Restoration: - focal Sand, Ec bags, Brick Vota etcii) Equipment/Tools Being Used in Restoration Works: - Tractor with tralley, loller Jeller Bestored Length
iii) Restored Length In open Area :- 24.5m
In habitation Area:-
iv) If Restoration work done in habitation Area give Reason :-
3. For Bridge (Size of Bridge/Culvert)
1) Damage Location/Chainage:-
2) No. of Span Damage:-
3) Length of Span:-
Nature of Damage (Pier/Abuttment/
/ing Wall/Approach Road Damage) :-
5) Details of Restoration :-
) Material Being Used in Restoration:-
i) Equipment/Tools Being Used in Restoration Works:-
ii) Restored Length:-
werall Grade of Restoration work (Satisfactory/Unsatisfactory):- Samples
Signature of Inspector
Official Seal)