INSPECTION REPORT FOR MOTORABLE WORK

| Jame of PIUs: - EE. RWD. Works Division Ararig |
|--|
| Jame of Block/Road: - Palast/ PM4SY to Bangama tolg tak |
| A. For Road |
| . Damage Location/Chainage: 0.500, 0.600, 1300 and 1350 km |
| Domaga I anati |
| |
| Nature of Damage (Length Wise) (i) Breach:- |
| (ii) Crust Damage :- |
| whether traffic fully/Partialiy obstructed:- Fully obstruct |
| 1. Details of Restoration: |
| i) Material Being Used in Restoration: - Local Sand, EC hage, brick bets, sope |
| (ii) Equipment/Tools Being Used in Restoration Works:- Tractos, TCB |
| (iii) Restored Length In open Area:- |
| In habitation Area:- |
| (iv) If Restoration work done in habitation Area give Reason:- |
| B. For Bridge (Size of Bridge/Culvert) |
| (1) Damage Location/Chainage:- |
| (2) No. of Span Damage:- |
| (3) Length of Span:- |
| (4) Nature of Damage (Pier/Abuttment/ |
| Wing Wall/Approach Road Damage):- |
| (5) Details of Restoration:- |
| (i) Material Being Used in Restoration :- |
| (ii) Equipment/Tools Being Used in Restoration Works:- |
| (iii) Restored Length :- |
| |
| Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory |
| 6 |
| Allers 1-1111mg |
| Signature of Inspector |
| (Official Seal) |