INSPECTION REPORT FOR MOTORABLE WORK

	MI FOR MOTORABLE WORK
Name of PIUs:- EE RWA	works Division Anonia
Name of Block/Road :- Jokih	et 1 Phulpur Road De Phulpur Pari tola
A. For Road	
Y A! 1/01 - 1	At ch - 1.1 Km
2. Damage Length: 37m	
	(i) Breach:- Breach Damage (ii) Crust Damage:- Grunt Damage (iii) Only Flank Damage:-
whether traffic fully/Partialiy obstruc	
4. Details of Restoration :-	V
(i) Material Being Used in Restoratio	n: Tucol Sand, Combon Piling, Ectog, Brick
(ii) Equipment/Tools Being Used in I	n:- Pocal Sand, Comboo Piling, Ectog, Brick Restoration Works:- Tractor with trolley, JCD follows In open Area:- Open Arrea
(iii) Restored Length	In open Area:- Open Area
	In habitation Area :-
(iv) If Restoration work done in habit	ation Area give Reason:-
B. For Bridge (Size of Bridge/Cu	lvert)
(1) Damage Location/Chainage :-	
(2) No. of Span Damage:-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttmer Wing Wall/Approach Road Damage)	
(5) Details of Restoration:-	
i) Material Being Used in Restoration	
(ii) Equipment/Tools Being Used in R	Restoration Works:-
(iii) Restored Length :-	
Overall Grade of Restoration work	(Satisfactory/Unsatisfactory):- Satisfactory
	,

क्रिक्रानिम् क्रिक्रा

Signature of Inspector
(Official Seal)