

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RHD, Works Division - Araria

Name of Block/Road :- Araria / Chaturanand Chaudhary Ke Ghat to Nymal Gola.

A. For Road

1. Damage Location/Chainage :- 2.150 km, 1.950, 1.930

2. Damage Length :- 36 mtr.

3. Nature of Damage (Length Wise) (i) Breach :- ~~Breach~~ Cudding
(ii) Crust Damage :- Crust damage.
(iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :- Partially

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Local Sand, Ec Bag, Bamboo, Brick Batts, etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with trolley, KB, Roller, etc

(iii) Restored Length In open Area :- 36 mtr.
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Cupre
11/11/29

11/11/29

Signature of Inspector
(Official Seal)