

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- P.W.D. work Division Lathisara Kharagpur, Garapur

Name of Block/Road :- Motorable Road from Ramchandrapur Badhi to 9

A. For Road to Koyawa Bina to P.M.G.S.Y Road

1. Damage Location / Chainage:- 0.15 KM to 0.25 KM

2. Damage Length 59m

3. Nature of Damage (Length wise)

(i) Breach :- 40m

(ii) Crust Damage :- 19m

(iii) Only Flank Damage

Whether Traffic Fully/Partialily Obstructed :-

4. Details of Restoration

(i) Material Being Used in Restoration :- Brick bats, GSB grit

(ii) Equipment/ Tools being Used in Restoration Works :- Tractor, J.C.B, Roller

(iii) Restored Length

In Open Area :- 59m

In Habitation Area :-

(iv) If Restoration work done in habitation Area Give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1. Damage Location / Chainage:-

2. No. of Span Damage

3. Length of Span

4. Nature of Damage (Pier/ Abutment/Wing wall/Approach Road Damage)

5. Details of Restoration

(i) Material Being Used in Restoration :-

(ii) Equipment/ Tools being Used in Restoration Works :-

(iii) Restored Length

In Open Area :-

In Habitation Area :-

Overall Grade of Restoration Work (Satisfactory/Unsatisfactory)

1/11/24
Jt

Signature of Inspector
(Official Seal)