

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD, Works Division Araria

Name of Block/Road :- Palasi / PWD High School via Santhal tola to Gherma
Vani Durg

A. For Road

1. Damage Location/Chainage :- 0.00 km

2. Damage Length :- 55m 41 m

3. Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage :-
(iii) Only Flank Damage :- } N/A

whether traffic fully/Partialiy obstructed :-

4. Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length In open Area :-
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :- 0.00 km

(2) No. of Span Damage :- 2 span

(3) Length of Span :- 8 m

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :- Approach road damage

(5) Details of Restoration :-

(i) Material Being Used in Restoration :- Local sand, Ec bags, brick bats, bamboo etc

(ii) Equipment/Tools Being Used in Restoration Works :- TTD tractor

(iii) Restored Length :- 55m 41 m

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector
(Official Seal)