INSPECTION REPORT FOR MOTORABLE WORK

Name of PILIS: - E E PLIA LICENTE TO COR
Name of PIUs: - EE RWD, Morks Division - Aranga
Name of Block/Road: - Jokichal
A. For Road
1. Damage Location/Chainage: Af Ch. O. Thm, O. 8km, 2.15km, 2.25km
2. Daniage Length :- 9n
3. Nature of Damage (Length Wise) (i) Breach:- Breach Damage (ii) Crust Damage:- Crust Damage (iii) Only Flank Damage:- Flank Damage
(ii) Crust Damage:- (nun + Comman)
(iii) Only Flank Damage:- Flank & ameas
4. Details of Restoration:
(1) Material Being Used in Restoration:-Local Sand, Bamboo, Ec Bog, Bricks Rus, e
(i) Material Being Used in Restoration:-Local Sand, Bamboo, Ec Bog, Bricks Rus, e (ii) Equipment/Tools Being Used in Restoration Works:-Tractor with frolly JCR, Polle (iii) Restored Length
(iii) Restored Length In open Area:- open onea In habitation Area:
III liaultation Area :-
iv) If Restoration work done in habitation Area give Reason :-
B. For Bridge (Size of Bridge/Culvert)
1) Damage Location/Chainage:-
2) No. of Span Damage :-
3) Length of Span :-
4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage):-
5) Details of Restoration:-
i) Material Being Used in Restoration:-
ii) Equipment/Tools Being Used in Restoration Works :-
iii) Restored Length:-
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):-Satisfactory
6
(Jun c) jil) ry
Signature of Inspector (Official Seal)
(Official Seal)