

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Works Division Anand

Name of Block/Road :- Palasi / Bhargona Mor to Naniya tola

A. For Road

1. Damage Location/Chainage :- 0.400 km, 0.450 km, 0.470 km, 0.500 km, 1.5 km

2. Damage Length :- 51.5 m

3. Nature of Damage (Length Wise) (i) Breach :- Breach cutting
(ii) Crust Damage :- Crust Damage
(iii) Only Flank Damage :- Flank cutting

whether traffic fully/Partially obstructed :- Fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Local sand, Bamboo, Ec bags etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with pulley, JCB, Roller etc

(iii) Restored Length In open Area :- 51.5 m
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1) Damage Location/Chainage :-

2) No. of Span Damage :-

3) Length of Span :-

4) Nature of Damage (Pier/Abutment/
Ving Wall/Approach Road Damage) :-

5) Details of Restoration :-

i) Material Being Used in Restoration :-

ii) Equipment/Tools Being Used in Restoration Works :-

iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

S. K. Singh
08/11/24

CPD
09/11/24

Signature of Inspector
(Official Seal)