

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWA Works Division Anania

Name of Block/Road :- Palosi / Kankhudia PWD road to Ganghali Barad
botta road

A. For Road

1. Damage Location/Chainage :- 1.00 km

2. Damage Length :- 15m

3. Nature of Damage (Length Wise)

(i) Breach :-	✓
(ii) Crust Damage :-	
(iii) Only Flank Damage :-	

whether traffic fully/Partialiy obstructed :- Fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick bats, Local sand, EC bags etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor, JCD

(iii) Restored Length

In open Area :- ✓

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

} N/A

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector
(Official Seal)

10/11/24
SD

10/11/24