

# INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- RWD WORKS DIVISION, NARGACHHIA	
Name of Block / Road :- JSMILEPUR / KALA MANDAR MIDDLE SCHOOL DIMHA NARAYANPUR TO PRIMARY SCHOOL NARAYANPUR DIMHA	
<b>A. For Road</b>	
0-90m, 120-150m, 200-320m, 360-400m	
1. Damage Location / Chainage : 120-150m, 200-320m, 360-400m	
2. Damage Length : $77.2\text{ m} + 172.5\text{ m} = 249.7\text{ m}$	
3. Nature of Damage (length wise)	(i) Breach :-
	(ii) Crust Damage :- 172.50 m
	(iii) Only Flank Damage - 77.2 m
whether traffic fully/Partialily obstructed - <del>Part</del> Fully obstructed	
<b>4. Details of Restoration :</b>	
(i) Material Being Used in Restoration : New bag and N.C, E.C bag, Sand bag	
(ii) Equipment / Tools being Used in Restoration Works : Front end Loader, roller	
(iii) Restored length	In open Area :- 249.7 m
	In habitation Area :-
(iv) if Restoration work done in habitation Area give Reason :- -	
<b>B. For Bridge (Size of Bridge / Culvert)</b>	
1. Damage Location / Chainage : -	
2. No. of Span Damage :- -	
3 Length of Span -	
4 Nature of Damage (Pier / Abutment/Wing wall/Approach Road Damage) -	
5. Details of Restoration : -	
(i) Material Being Used in Restoration : -	
(ii) Equipment / Tools being Used in Restoration Works : -	
(iii) Restored length	In open Area :- -
	In habitation Area :- -
Overall Grade of Restoration Work (Satisfactory / Unsatisfactory) Satisfactory.	

GR  
14/11/24  
JE

14/11/24

Shw  
14/11/24

Signature of Inspector  
(Official Seal)  
Executive Engineer  
RWD Works Division  
BANKA-1