

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWA Works Division Anaria

Name of Block/Road :- Kunsakanta / PCC Road to WN-06

A. For Road

1. Damage Location/Chainage :- 300 m

2. Damage Length :- 18 m

3. Nature of Damage (Length Wise) (i) Breach :- Breach Cutting
(ii) Crust Damage :- Crust Damage
(iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :- Fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Bamboo Piles, Local Sand, Brick Bats

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with trolley, Roller TCD etc

(iii) Restored Length
In open Area :- 18 m open Area
In habitation Area :- —

(iv) If Restoration work done in habitation Area give Reason :- —

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

11/11/24

11/11/24

18/11/24
Signature of Inspector
(Official Seal)