INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- EE W	sorus Airioin Anonia
Name of Block/Road :- kw	sorus sirioion Anonia sociatio Pus nood Thana Chowk to Gogne Gile
A. For Road - 7	Tarabari
1. Damage Location/Chainage :-	7.5 Km 0.9 km
2. Damage Length:- 11.	5 m
3. Nature of Damage (Length W	
	(ii) Crust Damage :-
	(iii) Only Flank Damage :-
whether traffic fully/Partialiy ob	structed:- fully
4. Details of Restoration:-	
(i) Material Being Used in Resto	ration: - Sand bag, Dambur, Drick bet etc
(ii) Equipment/Tools Being Used	d in Restoration Works: - Tractor, JCB etc
(iii) Restored Length	In open Area:-
	In habitation Area:-
(iv) If Restoration work done in	habitation Area give Reason:-
B. For Bridge (Size of Bridg	e/Culvert)
(1) Damage Location/Chainage	:-
(2) No. of Span Damage:-	
(3) Length of Span:-	
(4) Nature of Damage (Pier/Abu	ittment/
Wing Wall/Approach Road Dan	nage):-
(5) Details of Restoration:-	
(i) Material Being Used in Resto	
(ii) Equipment/Tools Being Use	d in Restoration Works:-
(iii) Restored Length:-	
Overall Grade of Restoration	work (Satisfactory/Unsatisfactory) :- Satisfactory
	10m 2 18/11/24
0	Signature of Inspector
On and	(Official Seal)