

# INSPECTION REPORT FOR MOTORABLE WORK

|                                                                                                   |                                         |
|---------------------------------------------------------------------------------------------------|-----------------------------------------|
| Name of PIUs :- EE RWD WORKS Division Anaria                                                      |                                         |
| Name of Block/Road :- Tukihat / Rani chowk Rani Basti PWD Road Rani Basti to Pathara wari Binwari |                                         |
| <b>A. For Road</b>                                                                                |                                         |
| 1. Damage Location/Chainage :- At Ch - 0.200 km                                                   |                                         |
| 2. Damage Length :- 22 mtr                                                                        |                                         |
| 3. Nature of Damage (Length Wise)                                                                 | (i) Breach :- Breach Damage             |
|                                                                                                   | (ii) Crust Damage :- Crust Damage       |
|                                                                                                   | (iii) Only Flank Damage :- Flank Damage |
| whether traffic fully/Partialiy obstructed :- fully                                               |                                         |
| <b>4. Details of Restoration :-</b>                                                               |                                         |
| (i) Material Being Used in Restoration :- Local Sand, Bamboo Piling, Ec bags, Brick bats etc      |                                         |
| (ii) Equipment/Tools Being Used in Restoration Works :- Tractor with Trolley, JCB, Roller etc     |                                         |
| (iii) Restored Length                                                                             | In open Area :- open Area               |
|                                                                                                   | In habitation Area :-                   |
| (iv) If Restoration work done in habitation Area give Reason :-                                   |                                         |
| <b>B. For Bridge (Size of Bridge/Culvert)</b>                                                     |                                         |
| (1) Damage Location/Chainage :-                                                                   |                                         |
| (2) No. of Span Damage :-                                                                         |                                         |
| (3) Length of Span :-                                                                             |                                         |
| (4) Nature of Damage (Pier/Abuttment/ Wing Wall/Approach Road Damage) :-                          |                                         |
| (5) Details of Restoration :-                                                                     |                                         |
| (i) Material Being Used in Restoration :-                                                         |                                         |
| (ii) Equipment/Tools Being Used in Restoration Works :-                                           |                                         |
| (iii) Restored Length :-                                                                          |                                         |
| Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory                   |                                         |

*[Signature]*  
2/11/24

*[Signature]*  
6/11/24

*[Signature]*  
19/11/24  
Signature of Inspector  
(Official Seal)