INSPECTION REPORT FOR MOTORABLE WORK

Ivalite of PIUS:- E.E. RWD, WALL DISC.	
Name of Plus: - E.E. RWD. Work Division Araria Name of Block/Road: - Palasi/ Maldwar to Kachhmoh Ghat A. For Road	
A. For Road	
1. Damage Location/Chainage:	
2 Damage Langel	
3. Nature of Damage (Length Wise) (i) Breach :-	
(ii) Crust Damage :-	
whether traffic fully/Partialiy obstructed:	
4. Details of Restaurtion	ſ
(i) Material Being Used in Restoration	
(ii) Faving and The in The color of the cal sand, EC bag, book but, on	pe esz
(i) Material Being Used in Restoration: Local Sand, Elbap, book but, on (ii) Equipment/Tools Being Used in Restoration Works: JCB, tractor (iii) Restored Length	
(iii) Restored Length In open Area:-	
In habitation Area:-	
(iv) If Restoration work done in habitation Area give Reason:	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
2) No. of Span Damage :-	
3) Length of Span:-	
4) Nature of Damage (Pier/Abuttment/	
Ving Wall/Approach Road Damage) :-	
5) Details of Restoration:-	
) Material Being Used in Restoration :-	
i) Equipment/Tools Being Used in Restoration Works :-	
ii) Restored Length :-	
verall Grade of Restoration work (Satisfactory/Unsatisfactory):- Sabar	Rely
Signature of Inspector (Official Seal)	