

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- R.W.D (W) Div. Lakhsarai Kharagpur, Darapur.
Name of Block/Road :- Motorable Road from Adarsh Laxmipur to Lal Digra

A. For Road

1. Damage Location / Chainage:- 6.5 KM

2. Damage Length 82 m

| | |
|-----------------------------------|---------------------------|
| 3. Nature of Damage (Length wise) | (i) Breach :- 63 m |
| | (ii) Crust Damage :- 19 m |
| | (iii) Only Flank Damage |

Whether Traffic Fully/Partialily Obstructed :-

4. Details of Restoration

(i) Material Being Used in Restoration :- Brck balt, GSB.

(ii) Equipment/ Tools being Used in Restoration Works :- Tractor, J.E.B, Roller

| | |
|-----------------------|-----------------------|
| (iii) Restored Length | In Open Area :- 82 m |
| | In Habitation Area :- |

(iv) If Restoration work done in habitation Area Give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1. Damage Location / Chainage:-

2. No. of Span Damage

3. Length of Span

4. Nature of Damage (Pier/ Abutment/Wing wall/Approach Road Damage)

5. Details of Restoration

(i) Material Being Used in Restoration :-

(ii) Equipment/ Tools being Used in Restoration Works :-

| | |
|-----------------------|-----------------------|
| (iii) Restored Length | In Open Area :- |
| | In Habitation Area :- |

Overall Grade of Restoration Work (Satisfactory/Unsatisfactory)

12/11/24
SK

Signature of Inspector
(Officail Seal)