## INSPECTION REPORT FOR MOTORABLE WORK

the state of the s	
Name of PIUs:- EE R	WA Works Division Anania
Name of Block/Road :- Joui	not 1 Bhunn-Pachaili - saidpur
A. For Road	
1. Damage Location/Chainage :-	A1 ch. 0.9 km, 1.1 km
2. Damage Length:- 37 m	1/
	(i) Breach: Breach Damage
5.114	(ii) Crust Damage: - Crust Damage
	(iii) Only Flank Damage:-
whether traffic fully/Partialiy obstru	
4. Details of Restoration:-	
(i) Material Being Used in Restorat	ion: Local Sand, Bamboo Piling, Echog Restoration Works: JCB, Rollon, Tractor with
(ii) Equipment/Tools Being Used in	Restoration Works: - JCB, Rollon, Tractor with
(iii) Restored Length	In open Area: whom Avec.
	In habitation Area:-
(iv) If Restoration work done in hab	oitation Area give Reason:-
B. For Bridge (Size of Bridge/C	Culvert)
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttm	ent/
Wing Wall/Approach Road Damage	e) :-
(5) Details of Restoration:-	
i) Material Being Used in Restorati	on:-
ii) Equipment/Tools Being Used in	Restoration Works:-
iii) Restored Length :-	
Overall Grade of Restoration wor	rk (Satisfactory/Unsatisfactory):- Sa his fails
	M. JUM
	Signature of Inspector (Official Seal)
930 19	y Gfficial Seal)
100.2011	