

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD WORK Division Baisi

Name of Block/Road Amour / NH 57 Kasba Gerva to Nalopara Bamma Dhar

A. For Road

1. Damage Location/Chainage :- 0.250 Km

2. Damage Length :- 35.00 mtr

| | |
|-----------------------------------|----------------------------|
| 3. Nature of Damage (Length Wise) | (i) Breach :- 35.00 mtr |
| | (ii) Crust Damage :- |
| | (iii) Only Flank Damage :- |

whether traffic fully/Partialy obstructed :- Fully obstructed

4. Details Of Restoration :-

(i) Material Being Used in Restoration :- Brick Bats

(ii) Equipment/Tools Being used in Restoration Work :- JCB, Tractor

| | |
|--------------------------|------------------------|
| (iii) Restoration Length | In Open Area 35.00 mtr |
| | In Habitation Area :- |

B. For Bridge (Size Of Bridge/Culvert)

1. Damage Location/Chainage :-

2. No. Span Damage :-

3. Length of Span :-

4. Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage)

5. Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being used in Restoration Work :-

(iii) Restored Length :-

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :-

Signature Of Inspection
(Official Seal)

असंबद्ध कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, पूर्णियाँ